



**US Army Corps  
of Engineers®**

# Flood Damage Reduction Segment / System Inspection Report

Name of Segment / System: Bolivar, NY

Public Sponsor(s): NY State Department of Environmental Conservation

Public Sponsor Representative: Theodore Myers

Sponsor Phone: 716-851-7070

Sponsor Email: Theodore.Myers@dec.ny.gov

Corps of Engineers Inspector: Brian Grogan Inspection Start Date: 10/21/2015

Inspection End Date: 10/27/2015

Inspection Report Prepared By: Brian Grogan Checked By: \_\_\_\_\_ Date Report Prepared: \_\_\_\_\_

Internal Technical Review (for Periodic Inspections) By: \_\_\_\_\_ Date of ITR: \_\_\_\_\_

Final Approved By: \_\_\_\_\_ Date Approved: \_\_\_\_\_

Type of Inspection:	<input type="checkbox"/> <b>Initial Eligibility Inspection</b> <input checked="" type="checkbox"/> <b>Continuing Eligibility Inspection (Routine)</b> <input type="checkbox"/> <b>Continuing Eligibility Inspection (Periodic)</b>	Overall Segment / System Rating: <input type="checkbox"/> <b>Acceptable</b> <input checked="" type="checkbox"/> <b>Minimally Acceptable</b> <input type="checkbox"/> <b>Unacceptable</b>
Contents of Report:	<input checked="" type="checkbox"/> <b>Instructions</b> <input type="checkbox"/> <b>Initial Eligibility Inspection</b> <input checked="" type="checkbox"/> <b>General Items for All Flood Control Works</b> <input checked="" type="checkbox"/> <b>Levee Embankment</b> <input type="checkbox"/> <b>Concrete Floodwalls</b> <input type="checkbox"/> <b>Sheet Pile and Concrete I-walls</b> <input checked="" type="checkbox"/> <b>Interior Drainage System</b> <input type="checkbox"/> <b>Pump Stations</b> <input checked="" type="checkbox"/> <b>FDR System Channels</b>	<p>Note: In addition to the report contents indicated here, a plan view drawing of the system, with stationing, should be included with this report to reference locations of items rated less than acceptable. Photos of general system condition and any noted deficiencies should also be attached.</p> <p>Note: This inspection rating represents the Corps evaluation of operations and maintenance of the flood damage reduction system and may be used in conjunction with other information for a levee certification determination for National Flood Insurance Program (NFIP) purposes if applicable. An Acceptable Corps inspection rating, alone, does not equate to a certifiable levee for the NFIP. It is recommended for levee systems currently accredited by the Federal Emergency Management Agency (FEMA) for NFIP purposes receiving a Corps Minimally Acceptable or Unacceptable rating, be evaluated by the levee owner to determine the potential impacts to the certification for FEMA.</p>



**US Army Corps  
of Engineers®**

# **Flood Damage Reduction Segment / System Public Sponsor Pre-Inspection Form**

The following information is to be provided by the levee district sponsor prior to an inspection. This information will be used to help evaluate the organizational capability of the levee district to manage the levee segment / system maintenance program.

<b>1. Levee segment / system and district: (name of the segment / system and levee district)</b> Bolivar, NY for CELRP
<b>2. Reporting period: (month/day/year to month/day/year)</b> 11/7/2013 - 10/21/2015
<b>3. Summary of maintenance required by last inspection report:</b> Remove vegetation within easement limits Remove small sediment bar Monitor and repair gabion baskets
<b>4. Summary of maintenance performed this reporting period:</b> Vegetation maintenance
<b>5. Summary of maintenance planned next reporting period:</b> Vegetation maintenance Debris removal Flap gate repair
<b>6. Summary of changes to segment / system since last inspection:</b> The debris basin (upstream end of project) was realigned in 2001/2002 along with riprap slope protection and a concrete wall to prevent undermining of the bank
<b>7. Problems/ issues requiring the assistance of the US Army Corps of Engineers:</b>



US Army Corps  
of Engineers®

**Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)**

**Pre-Inspection Form  
Page 1 of 2**

# Public Sponsor Pre-Inspection Report

The following information is to be provided by the levee district sponsor prior to an inspection

8. Levee district organization: (elected or appointed levee district officials and key employees)

Name	Position	Mailing Address	Phone Number	Email Address
Theodore Myers	Environmental Engineer 2	270 Michigan Ave, Buffalo, NY 14203	716-851-7070	Theodore.Myers@dec.ny.gov

# General Instructions for the Inspection of Flood Damage Reduction Segments / Systems

## A. Purpose of USACE Inspections:

The primary purpose of these inspections is to prevent loss of life and catastrophic damages; preserve the value of Federal investments, and to encourage non-Federal sponsors to bear responsibility for their own protection. Inspections should assure that Flood Damage Reduction structures and facilities are continually maintained and operated as necessary to obtain the maximum benefits. Inspections are also conducted to determine eligibility for Rehabilitation Assistance under authority of PL 84-99 for Federal and non-Federal systems. (ER 1130-2-530, ER 500-1-1)

## B. Types of Inspections:

The Corps conducts several types of inspections of Flood Damage Reduction systems, as outlined below:

Initial Eligibility Inspections	Continuing Eligibility Inspections	
	Routine Inspections	Periodic Inspections
IEIs are conducted to determine whether a non-Federally constructed Flood Damage Reduction system meets the minimum criteria and standards set forth by the Corps for initial inclusion into the Rehabilitation and Inspection Program.	RIs are intended to verify proper maintenance, owner preparedness, and component operation.	PIs are intended to verify proper maintenance and component operation and to evaluate operational adequacy, structural stability, and safety of the system. Periodic Inspections evaluate the system's original design criteria vs. current design criteria to determine potential performance impacts, evaluate the current conditions, and compare the design loads and design analysis used against current design standards. This is to be done to identify components and features for the sponsor that need to be monitored more closely over time or corrected as needed. (Periodic Inspections are used as the basis of risk assessments.)

## C. Inspection Boundaries:

Inspections should be conducted so as to rate each Flood Damage Reduction "Segment" of the system. The overall system rating will be the lowest segment rating in the system.

Project	System	Segment
A flood damage reduction project is made up of one or more flood damage reduction systems which were under the same authorization.	A flood damage reduction system is made up of one or more flood damage reduction segments which collectively provide flood damage reduction to a defined area. Failure of one segment within a system constitutes failure of the entire system. Failure of one system does not affect another system.	A flood damage reduction segment is defined as a discrete portion of a flood damage reduction system that is operated and maintained by a single entity. A flood damage reduction segment can be made up of one or more features (levee, floodwall, pump stations, etc).

## D. Land Use Definitions:

The following three definitions are intended for use in determining minimum required inspection intervals and initial requirements for inclusion into the Rehabilitation and Inspection Program. Inspections should be considered for all systems that would result in significant environmental or economic impact upon failure regardless of specific land use.

Agricultural	Rural	Urban
Protected population in the range of zero to 5 households per square mile protected.	Protected population in the range of 6 to 20 households per square mile protected.	Greater than 20 households per square mile; major industrial areas with significant infrastructure investment. Some protected urban areas have no permanent population but may be industrial areas with high value infrastructure with no overnight population.

**E. Use of the Inspection Report Template:**

The report template is intended for use in all Army Corps of Engineers inspections of levee and floodwall systems and flood damage reduction channels. The section of the template labeled "Initial Eligibility" only needs to be completed during Initial Eligibility Inspections of Non-Federally constructed Flood Damage Reduction Systems. The section labeled "General Items" needs to be completed with every inspection, along with all other sections that correspond to features in the system. The section labeled "Public Sponsor Pre-Inspection Report" is intended for completion before the inspection, if possible.

**F. Individual Item / Component Ratings:**

Assessment of individual components rated during the inspection should be based on the criteria provided in the inspection report template, though inspectors may incorporate additional items into the report based on the characteristics of the system. The assessment of individual components should be based on the following definitions.

Acceptable Item	Minimally Acceptable Item	Unacceptable Item
The inspected item is in satisfactory condition, with no deficiencies, and will function as intended during the next flood event.	The inspected item has one or more minor deficiencies that need to be corrected. The minor deficiency or deficiencies will not seriously impair the functioning of the item as intended during the next flood event.	The inspected item has one or more serious deficiencies that need to be corrected. The serious deficiency or deficiencies will seriously impair the functioning of the item as intended during the next flood event.

**G. Overall Segment / System Ratings:**

Determination of the overall system rating is based on the definitions below. Note that an Unacceptable System Rating may be either based on an engineering determination that concluded that noted deficiencies would prevent the system from functioning as intended during the next flood event, or based on the sponsor's demonstrated lack of commitment or inability to correct serious deficiencies in a timely manner.

Acceptable System	Minimally Acceptable System	Unacceptable System
All items or components are rated as Acceptable.	One or more items are rated as Minimally Acceptable or one or more items are rated as Unacceptable and an engineering determination concludes that the Unacceptable items would not prevent the segment / system from performing as intended during the next flood event.	One or more items are rated as Unacceptable and would prevent the segment / system from performing as intended, or a serious deficiency noted in past inspections (which had previously resulted in a minimally acceptable system rating) has not been corrected within the established timeframe, not to exceed two years.

**H. Eligibility for PL84-99 Rehabilitation Assistance:**

Inspected systems that are not operated and maintained by the Federal government may be Active in the Corps' Rehabilitation and Inspection Program (RIP) and eligible for rehabilitation assistance from the Corps as defined below:

If the Overall System Rating is Acceptable	If the Overall System Rating is Minimally Acceptable	If the Overall System Rating is Unacceptable
The system is active in the RIP and eligible for PL84-99 rehabilitation assistance.	The system is Active in the RIP during the time that it takes to make needed corrections. Active systems are eligible for rehabilitation assistance. However, if the sponsor does not present USACE with proof that serious deficiencies (which had previously resulted in a minimally acceptable system rating) were corrected within the established timeframe, then the system will become Inactive in the RIP.	The system is Inactive in the RIP, and the status will remain Inactive until the sponsor presents USACE with proof that all items rated Unacceptable have been corrected. Inactive systems are ineligible for rehabilitation assistance.

**I. Reporting:**

After the inspection, the Corps is responsible for assembling an inspection report (or a summary report if it was a Periodic Inspection) including the following information:

- a. All sections of the report template used during the inspection, including the cover and pre-inspection materials. (Supplemental data collected, and any sections of the template that weren't used during the inspection do not need to be included with the report.)
- b. Photos of the general system condition and noted deficiencies.
- c. A plan view drawing of the system, with stationing, to reference locations of items rated less than acceptable.
- d. The relative importance of the identified maintenance issues should be specified in the transmittal letter.
- e. If the Overall System Rating is Minimally Acceptable, the report needs to establish a timeframe for correction of serious deficiencies noted (not to exceed two years) and indicate that if these items are not corrected within the required timeframe, the system will be rated as Unacceptable and made Inactive in the Rehabilitation Inspection Program.

**J. Notification:**

Reports are to be disseminated as follows within 30 days of the inspection date.

If the Overall System Rating is Acceptable	If the Overall System Rating is Minimally Acceptable	If the Overall System Rating is Unacceptable
Reports need to be provided to the local sponsor and the county emergency management agency.	Reports need to be provided to the local sponsor, state emergency management agency, county emergency management agency, and to the FEMA region.	Reports need to be provided to the local sponsor, state emergency management agency, county emergency management agency, FEMA region, and to the Congressional delegation within 30 days of the inspection.

## General Items for All Flood Damage Reduction Segments / Systems

For use during all inspections of all Flood Damage Reduction Segments / Systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
1. Operations and Maintenance Manuals	<b>A</b>	<b>A</b>	Levee Owner's Manual, O&M Manuals, and/or manufacturer's operating instructions are present.	
		<b>M</b>	Sponsor manuals are lost or missing or out of date; however, sponsor will obtain manuals prior to next scheduled inspection.	
		<b>U</b>	Sponsor has not obtained lost or missing manuals identified during previous inspection.	
2. Emergency Supplies and Equipment (A or M only)	<b>A</b>	<b>A</b>	The sponsor maintains a stockpile of sandbags, shovels, and other flood fight supplies which will adequately supply all needs for the initial days of a flood fight. Sponsor determines required quantity of supplies after consulting with inspector.	
		<b>M</b>	The sponsor does not maintain an adequate supply of flood fighting materials as part of their preparedness activities.	
3. Flood Preparedness and Training (A or M only)	<b>A</b>	<b>A</b>	Sponsor has a written system-specific flood response plan and a solid understanding of how to operate, maintain, and staff the FDR system during a flood. Sponsor maintains a list of emergency contact information for appropriate personnel and other emergency response agencies.	
		<b>M</b>	The sponsor maintains a good working knowledge of flood response activities, but documentation of system-specific emergency procedures and emergency contact personnel is insufficient or out of date.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

General Items for All Flood Damage Reduction  
Segments / Systems  
Page 1 of 1

# Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
1. Unwanted Vegetation Growth <sup>1</sup>	<b>M</b>	<b>A</b>	The levee has little or no unwanted vegetation (trees, bush, or undesirable weeds), except for vegetation that is properly contained and/or situated on overbuilt sections, such that the mandatory 3-foot root-free zone is preserved around the levee profile. The levee has been recently mowed. The vegetation-free zone extends 15 feet from both the landside and riverside toes of the levee to the centerline of the tree. If the levee access easement doesn't extend to the described limits, then the vegetation-free zone must be maintained to the easement limits. Reference EM 1110-2-301 or Corps policy for regional vegetation variance.	BOLI_2015_a_0041: Station_1 NA: Significant brushy vegetation (minimal woody vegetation); could not inspect the floodside of levee: Cut down tall brush from levee. (U)
		<b>M</b>	Minimal vegetation growth (brush, weeds, or trees 2 inches in diameter or smaller) is present within the zones described above. This vegetation must be removed but does not currently threaten the operation or integrity of the levee.	
		<b>U</b>	Significant vegetation growth (brush, weeds, or any trees greater than 2 inches in diameter) is present within the zones described above and must to be removed to reestablish or ascertain levee integrity.	
2. Sod Cover	<b>A</b>	<b>A</b>	There is good coverage of sod over the levee.	
		<b>M</b>	Approximately 25% of the sod cover is missing or damaged over a significant portion or over significant portions of the levee embankment. This may be the result of over-grazing or feeding on the levee, unauthorized vehicular traffic, chemical or insect problems, or burning during inappropriate seasons.	
		<b>U</b>	Over 50% of the sod cover is missing or damaged over a significant portion or portions of the levee embankment.	
		<b>N/A</b>	Surface protection is provided by other means.	
3. Encroachments	<b>A</b>	<b>A</b>	No trash, debris, unauthorized farming activity, structures, excavations, or other obstructions present within the easement area. Encroachments have been previously reviewed by the Corps, and it was determined that they do not diminish proper functioning of the levee.	Remove old football equipment from the permanent easement (See inspection ID 0041, photo 0041_4, near STA 21+00 sheet 038pa.1-P1-82/2). Push trailer out of the permanent easement area (See Photo 0032_1, near STA 37+00).
		<b>M</b>	Trash, debris, unauthorized farming activity, structures, excavations, or other obstructions present, or inappropriate activities noted that should be corrected but will not inhibit operations and maintenance or emergency operations. Encroachments have not been reviewed by the Corps.	
		<b>U</b>	Unauthorized encroachments or inappropriate activities noted are likely to inhibit operations and maintenance, emergency operations, or negatively impact the integrity of the levee.	
4. Closure Structures (Stop Log, Earthen Closures, Gates, or Sandbag	<b>NA</b>	<b>A</b>	Closure structure in good repair. Placing equipment, stoplogs, and other materials are readily available at all times. Components are clearly marked and installation instructions/ procedures readily available. Trial erections have been accomplished in accordance with the O&M Manual.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Levee Embankments  
Page 1 of 5



# Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
Closures) (A or U only)		U	Any of the following issues is cause for this rating: Closure structure in poor condition. Parts missing or corroded. Placing equipment may not be available within the anticipated warning time. The storage vaults cannot be opened during the time of inspection. Components of closure are not clearly marked and installation instructions/ procedures are not readily available. Trial erections have not been accomplished in accordance with the O&M Manual.	
		N/A	There are no closure structures along this component of the FDR segment / system.	
5. Slope Stability	A	A	No slides, sloughs, tension cracking, slope depressions, or bulges are present.	
		M	Minor slope stability problems that do not pose an immediate threat to the levee embankment.	
		U	Major slope stability problems (ex. deep seated sliding) identified that must be repaired to reestablish the integrity of the levee embankment.	
6. Erosion/ Bank Caving	A	A	No erosion or bank caving is observed on the landward or riverward sides of the levee that might endanger its stability.	BOLI_2015_a_0028: Station_1 NA: It is possible that the gabions immediately adjacent of the Davis St. bridge were removed to facilitate construction but not replaced resulting in erosion.: The eroded area is higher than the gabion dike, but will progress if left unmaintained. Repair eroded area and replace gabion dike up to Davis St. (A)
		M	There are areas where minor erosion is occurring or has occurred on or near the levee embankment, but levee integrity is not threatened.	
		U	Erosion or caving is occurring or has occurred that threatens the stability and integrity of the levee. The erosion or caving has progressed into the levee section or into the extended footprint of the levee foundation and has compromised the levee foundation stability.	
7. Settlement <sup>2</sup>	A	A	No observed depressions in crown. Records exist and indicate no unexplained historical changes.	
		M	Minor irregularities that do not threaten integrity of levee. Records are incomplete or inclusive.	
		U	Obvious variations in elevation over significant reaches. No records exist or records indicate that design elevation is compromised.	
8. Depressions/ Rutting	A	A	There are scattered, shallow ruts, pot holes, or other depressions on the levee that are unrelated to levee settlement. The levee crown, embankments, and access road crowns are well established and drain properly without any ponded water.	
		M	There are some infrequent minor depressions less than 6 inches deep in the levee crown, embankment, or access roads that will pond water.	
		U	There are depressions greater than 6 inches deep that will pond water.	
9. Cracking	A	A	Minor longitudinal, transverse, or desiccation cracks with no vertical movement along the crack. No cracks extend continuously through the levee crest.	
		M	Longitudinal and/or transverse cracks up to 6 inches in depth with no vertical movement along the crack. No cracks extend continuously through the levee crest. Longitudinal cracks are no longer than the height of the levee.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Levee Embankments  
Page 2 of 5

# Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
		<b>U</b>	Cracks exceed 6 inches in depth. Longitudinal cracks are longer than the height of the levee and/or exhibit vertical movement along the crack. Transverse cracks extend through the entire levee width.	
10. Animal Control	<b>A</b>	<b>A</b>	Continuous animal burrow control program in place that includes the elimination of active burrowing and the filling in of existing burrows.	
		<b>M</b>	The existing animal burrow control program needs to be improved. Several burrows are present which may lead to seepage or slope stability problems, and they require immediate attention.	
		<b>U</b>	Animal burrow control program is not effective or is nonexistent. Significant maintenance is required to fill existing burrows, and the levee will not provide reliable flood protection until this maintenance is complete.	
11. Culverts/ Discharge Pipes <sup>3</sup> (This item includes both concrete and corrugated metal pipes.)	<b>NA</b>	<b>A</b>	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	Pipe under gabion dike (STA 41+50+/-) rated under interior drainage system, rated item 11. Flap gate associated with the protected side of this pipe is rated under flood damage reduction channel, rated item 9.
		<b>M</b>	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		<b>U</b>	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
		<b>N/A</b>	There are no discharge pipes/ culverts.	
12. Riprap Revetments &	<b>A</b>	<b>A</b>	No riprap displacement or stone degradation that could pose an immediate threat to the integrity of channel bank. Riprap intact with no woody vegetation present.	Gabion dike (STA 41+00 to 43+25 +/-)

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Levee Embankments  
Page 3 of 5

# Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
Bank Protection		<b>M</b>	Minor riprap displacement or stone degradation that could pose an immediate threat to the integrity of the channel bank. Unwanted vegetation must be cleared or sprayed with an appropriate herbicide.	
		<b>U</b>	Significant riprap displacement, exposure of bedding, or stone degradation observed. Scour activity is undercutting banks, eroding embankments, or impairing channel flows by causing turbulence or shoaling. Rock protection is hidden by dense brush, trees, or grasses.	
		<b>N/A</b>	There is no riprap protecting this feature of the segment / system, or riprap is discussed in another section.	
13. Revetments other than Riprap	<b>NA</b>	<b>A</b>	Existing revetment protection is properly maintained, undamaged, and clearly visible.	
		<b>M</b>	Minor revetment displacement or deterioration that does not pose an immediate threat to the integrity of the levee. Unwanted vegetation must be cleared or sprayed with an appropriate herbicide.	
		<b>U</b>	Significant revetment displacement, deterioration, or exposure of bedding observed. Scour activity is undercutting banks, eroding embankments, or impairing channel flows by causing turbulence or shoaling. Revetment protection is hidden by dense brush and trees.	
		<b>N/A</b>	There are no such revetments protecting this feature of the segment / system.	
14. Underseepage Relief Wells/ Toe Drainage Systems	<b>NA</b>	<b>A</b>	Toe drainage systems and pressure relief wells necessary for maintaining FDR segment / system stability during high water functioned properly during the last flood event and no sediment is observed in horizontal system (if applicable). Nothing is observed which would indicate that the drainage systems won't function properly during the next flood, and maintenance records indicate regular cleaning. Wells have been pumped tested within the past 5 years and documentation is provided.	
		<b>M</b>	Toe drainage systems or pressure relief wells are damaged and may become clogged if they are not repaired. Maintenance records are incomplete or indicate irregular cleaning and pump testing.	
		<b>U</b>	Toe drainage systems or pressure relief wells necessary for maintaining FDR segment / system stability during flood events have fallen into disrepair or have become clogged. No maintenance records. No documentation of the required pump testing.	
		<b>N/A</b>	There are no relief wells/ toe drainage systems along this component of the FDR segment / system.	
15. Seepage	<b>A</b>	<b>A</b>	No evidence or history of unrepaired seepage, saturated areas, or boils.	
		<b>M</b>	Evidence or history of minor unrepaired seepage or small saturated areas at or beyond the landside toe but not on the landward slope of levee. No evidence of soil transport.	
		<b>U</b>	Evidence or history of active seepage, extensive saturated areas, or boils.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Levee Embankments  
Page 4 of 5

# Levee Embankments

## For use during Initial and Continuing Eligibility Inspections of levee segments / systems

<sup>1</sup> If there is significant growth on the levee that inhibits the inspection of animal burrows or other items, the inspection should be ended until this item is corrected.

<sup>2</sup> Detailed survey elevations are normally required during Periodic Inspections, and whenever there are obvious visual settlements.

<sup>3</sup> The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

**Flood Damage Reduction Segment / System**  
**Inspection Report**  
**Bolivar, NY (BOLI)**

**Levee Embankments**  
**Page 5 of 5**

# Interior Drainage System

For use during Initial and Continuing Eligibility Inspections of interior drainage systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
1. Vegetation and Obstructions	<b>A</b>	<b>A</b>	No obstructions, vegetation, debris, or sediment accumulation noted within interior drainage channels or blocking the culverts, inlets, or discharge areas. Concrete joints and weep holes are free of grass and weeds.	
		<b>M</b>	Obstructions, vegetation, debris, or sediment are minor and have not impaired channel flow capacity or blocked more than 10% of any culvert openings, but should be removed. A limited volume of grass and weeds may be present in concrete channel joints and weep holes.	
		<b>U</b>	Obstructions, vegetation, debris, or sediment have impaired the channel flow capacity or blocked more than 10% of a culvert opening. Sediment and debris removal required to re-establish flow capacity.	
2. Encroachments	<b>A</b>	<b>A</b>	No trash, debris, unauthorized structures, excavations, or other obstructions present within the easement area. Encroachments have been previously reviewed by the Corps, and it was determined that they do not diminish proper functioning of the interior drainage system.	
		<b>M</b>	Trash, debris, unauthorized structures, excavations, or other obstructions present, or inappropriate activities noted that should be corrected but will not inhibit operations and maintenance or emergency operations. Encroachments have not been reviewed by the Corps.	
		<b>U</b>	Unauthorized encroachments or inappropriate activities noted are likely to inhibit operations and maintenance, emergency operations, or negatively impact the integrity of this component of the interior drainage system.	
3. Ponding Areas	<b>NA</b>	<b>A</b>	No trash, debris, structures, or other obstructions present within the ponding areas. Sediment deposits do not exceed 10% of capacity.	
		<b>M</b>	Trash, debris, excavations, structures, or other obstructions present, or inappropriate activities that will not inhibit operations and maintenance. Sediment deposits do not exceed 30% of capacity.	
		<b>U</b>	Trash, debris, excavations, structures, or other obstructions, or other encroachments or activities noted that will inhibit operations, maintenance, or emergency work. Sediment deposits exceeds 30% of capacity.	
		<b>N/A</b>	There are no ponding areas associated with the interior drainage system.	
4. Fencing and Gates <sup>1</sup>	<b>NA</b>	<b>A</b>	Fencing is in good condition and provides protection against falling or unauthorized access. Gates open and close freely, locks are in place, and there is little corrosion on metal parts.	
		<b>M</b>	Fencing or gates are damaged or corroded but appear to be maintainable. Locks may be missing or damaged.	
		<b>U</b>	Fencing and gates are damaged or corroded to the point that replacement is required, or potentially dangerous features are not secured.	
		<b>N/A</b>	There are no features noted that require safety fencing.	
5. Concrete Surfaces (Such as gate)	<b>NA</b>	<b>A</b>	Negligible spalling, scaling or cracking. If the concrete surface is weathered or holds moisture, it is still satisfactory but should be seal coated to prevent freeze/ thaw damage.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Interior Drainage System  
Page 1 of 5

# Interior Drainage System

For use during Initial and Continuing Eligibility Inspections of interior drainage systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
wells, outfalls, intakes, or culverts)		<b>M</b>	Spalling, scaling, and open cracking present, but the immediate integrity or performance of the structure is not threatened. Reinforcing steel may be exposed. Repairs/ sealing is necessary to prevent additional damage during periods of thawing and freezing.	
		<b>U</b>	Surface deterioration or deep cracks present that may result in an unreliable structure. Any surface deterioration that exposes the sheet piling or lies adjacent to monolith joints may indicate underlying reinforcement corrosion and is unacceptable.	
		<b>N/A</b>	There are no concrete items in the interior drainage system.	
6. Tilting, Sliding or Settlement of Concrete and Sheet Pile Structures <sup>2</sup> (Such as gate wells, outfalls, intakes, or culverts)	<b>NA</b>	<b>A</b>	There are no significant areas of tilting, sliding, or settlement that would endanger the integrity of the structure.	
		<b>M</b>	There are areas of tilting, sliding, or settlement (either active or inactive) that need to be repaired. The maximum offset, either laterally or vertically, does not exceed 2 inches unless the movement can be shown to be no longer actively occurring. The integrity of the structure is not in danger.	
		<b>U</b>	There are areas of tilting, sliding, or settlement (either active or inactive) that threaten the structure's integrity and performance. Any movement that has resulted in failure of the waterstop (possibly identified by daylight visible through the joint) is unacceptable. Differential movement of greater than 2 inches between any two adjacent monoliths, either laterally or vertically, is unacceptable unless it can be shown that the movement is no longer active. Also, if the floodwall is of I-wall construction, then any visible or measurable tilting of the wall toward the protected side that has created an open horizontal crack on the riverside base of a monolith is unacceptable.	
		<b>N/A</b>	There are no concrete items in the interior drainage system.	
7. Foundation of Concrete Structures <sup>3</sup> (Such as culverts, inlet and discharge structures, or gatewells.)	<b>NA</b>	<b>A</b>	No active erosion, scouring, or bank caving that might endanger the structure's stability.	
		<b>M</b>	There are areas where the ground is eroding towards the base of the structure. Efforts need to be taken to slow and repair this erosion, but it is not judged to be close enough to the structure or to be progressing rapidly enough to affect structural stability before the next inspection. The rate of erosion is such that the structure is expected to remain stable until the next inspection.	
		<b>U</b>	Erosion or bank caving observed that may lead to structural instabilities before the next inspection.	
		<b>N/A</b>	There are no concrete items in the interior drainage system.	
8. Monolith Joints	<b>NA</b>	<b>A</b>	The joint material is in good condition. The exterior joint sealant is intact and cracking/ desiccation is minimal. Joint filler material and/or waterstop is not visible at any point.	
		<b>M</b>	The joint material has appreciable deterioration to the point where joint filler material and/or waterstop is visible in some locations. This needs to be repaired or replaced to prevent spalling and cracking during freeze/ thaw cycles, and to ensure water tightness of the joint.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Interior Drainage System  
Page 2 of 5

# Interior Drainage System

For use during Initial and Continuing Eligibility Inspections of interior drainage systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
		<b>U</b>	The joint material is severely deteriorated or the concrete adjacent to the monolith joints has spalled and cracked, damaging the waterstop; in either case damage has occurred to the point where it is apparent that the joint is no longer watertight and will not provide the intended level of protection during a flood.	
		<b>N/A</b>	There are no monolith joints in the interior drainage system.	
9. Culverts/ Discharge Pipes <sup>4</sup>	<b>A</b>	<b>A</b>	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		<b>M</b>	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		<b>U</b>	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
		<b>N/A</b>	There are no discharge pipes/ culverts.	
10. Sluice / Slide Gates <sup>5</sup>	<b>NA</b>	<b>A</b>	Gates open and close freely to a tight seal or minor leakage. Gate operators are in good working condition and are properly maintained. Sill is free of sediment and other obstructions. Gates and lifters have been maintained and are free of corrosion. Documentation provided during the inspection.	
		<b>M</b>	Gates and/or operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions.	
		<b>U</b>	Gates do not open or close and/or operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion.	
		<b>N/A</b>	There are no sluice/ slide gates.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Interior Drainage System  
Page 3 of 5

# Interior Drainage System

For use during Initial and Continuing Eligibility Inspections of interior drainage systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
11. Flap Gates/ Flap Valves/ Pinch Valves <sup>1</sup>	<b>NA</b>	<b>A</b>	Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required.	Rated under flood damage reduction channel, rated item 9
		<b>M</b>	Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance.	
		<b>U</b>	Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced.	
		<b>N/A</b>	There are no flap gates.	
12. Trash Racks (non-mechanical)	<b>NA</b>	<b>A</b>	Trash racks are fastened in place and properly maintained.	
		<b>M</b>	Trash racks are in place but are unfastened or have bent bars that allow debris to enter into the pipe or pump station, bars are corroded to the point that up to 10% of the sectional area may be lost. Repair or replacement is required.	
		<b>U</b>	Trash racks are missing or damaged to the extent that they are no longer functional and must be replaced. (For example, more than 10% of the sectional area may be lost.)	
		<b>N/A</b>	There are no trash racks, or they are covered in the pump stations section of the report.	
13. Other Metallic Items	<b>NA</b>	<b>A</b>	All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern.	
		<b>M</b>	Corrosion seen on metallic parts appears to be maintainable.	
		<b>U</b>	Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	
		<b>N/A</b>	There are no other significant metallic items.	
14. Riprap Revetments of Inlet/ Discharge Areas	<b>NA</b>	<b>A</b>	No riprap displacement or stone degradation that could pose an immediate threat to the integrity of channel bank. Riprap intact with no woody vegetation present.	
		<b>M</b>	Minor riprap displacement or stone degradation that could pose an immediate threat to the integrity of the channel bank. Unwanted vegetation must be cleared or sprayed with an appropriate herbicide.	
		<b>U</b>	Significant riprap displacement, exposure of bedding, or stone degradation observed. Scour activity is undercutting banks, eroding embankments, or impairing channel flows by causing turbulence or shoaling. Rock protection is hidden by dense brush, trees, or grasses.	
		<b>N/A</b>	There is no riprap protecting this feature of the segment / system, or riprap is discussed in another section.	
15. Revetments other than Riprap	<b>NA</b>	<b>A</b>	No riprap displacement or stone degradation that could pose an immediate threat to the integrity of channel bank. Riprap intact with no woody vegetation present.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Interior Drainage System  
Page 4 of 5



# Interior Drainage System

For use during Initial and Continuing Eligibility Inspections of interior drainage systems

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
		<b>M</b>	Minor riprap displacement or stone degradation that could pose an immediate threat to the integrity of the channel bank. Unwanted vegetation must be cleared or sprayed with an appropriate herbicide.	
		<b>U</b>	Significant riprap displacement, exposure of bedding, or stone degradation observed. Scour activity is undercutting banks, eroding embankments, or impairing channel flows by causing turbulence or shoaling. Rock protection is hidden by dense brush, trees, or grasses.	
		<b>N/A</b>	There are no such revetments protecting this feature of the segment / system.	

<sup>1</sup> Proper operation of this item must be demonstrated during the inspection.

<sup>2</sup> The sponsor should be monitoring any observed movement to verify whether the movement is active or inactive.

<sup>3</sup> Inspectors must have as-built drawings available during the inspection so that the lateral distance to the heel and toe of the floodwalls can be determined in the field.

<sup>4</sup> The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

<sup>5</sup> Proper operation of the gates (full open and closed) must be demonstrated during the inspection if no documentation is available. Be aware of both manual and electrical operators.

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Interior Drainage System  
Page 5 of 5

# Flood Damage Reduction Channels

For use during Initial and Continuing Eligibility Inspections of flood damage reduction channels

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
1. Vegetation and Obstructions	<b>M</b>	<b>A</b>	No obstructions, vegetation, debris, or sediment accumulation within the channel. Concrete channel joints and weep holes are free of grass and weeds.	<p>BOLI_2015_a_0003: Station_1 NA: Vegetation should be mowed/controlled on the banks in the sedimentation area; refer to photo for inspection ID 0001.: NA (M)</p> <p>BOLI_2015_a_0004: Station_1 NA: From STA 62+30 to STA 59+00 - informational only; no improvements made: NA (A)</p> <p>BOLI_2015_a_0010: Station_1 NA: Small vegetation and small diameter tree through gabions.: Sponsor should remove the tree in the gabion area before it gets too large. Repair gabions after removal. (M)</p> <p>BOLI_2015_a_0012: Station_1 NA: Access ramp (STA 53+00 +/-) does not appear to be marked on as-built drawings.: NA (A)</p> <p>BOLI_2015_a_0013: Station_1 NA: Debris stockpile on top of bank. Could pose difficulty in O&amp;M and flood fighting capabilities.: Sponsor should remove debris pile from the right bank of Root Creek. (A)</p> <p>BOLI_2015_a_0014: Station_1 NA: Large diameter trees appear to be located outside of the project's permanent easement: NA (A)</p> <p>BOLI_2015_a_0016: Station_1 NA: Existing 9-ft wide concrete arch culvert (on as-builts at STA 51+75 +/-). May be outside of permanent easement but drains into Root Creek.: NA (A)</p> <p>BOLI_2015_a_0020: Station_1 NA: Old cast iron pipe with tree growing on top.: Recommend removing the tree from the bank. (M)</p> <p>BOLI_2015_a_0021: Station_1 NA: Large diameter tree.: Recommend removing the tree. (M)</p> <p>BOLI_2015_a_0029: Station_1 NA: Access ramp from Davis St to STA 39+00 +/-: NA (A)</p> <p>BOLI_2015_a_0032: Station_1 NA: Channel is not viewable due to vegetation: Recommend removing vegetation (M)</p> <p>BOLI_2015_a_0034: Station_1 NA: Pine trees are shown on the as-builts (near STA 33+00 - 32+00), but other vegetation make access difficult.: Recommend removing smaller brush in the permanent easement (M)</p> <p>BOLI_2015_a_0035: Station_1 NA: NYDOT drop structure (STA 27+50 +/-): NA (A)</p> <p>BOLI_2015_a_0036: Station_1 NA: Channel improvement in this area was completed by NYDOT.: NA (A)</p> <p>BOLI_2015_a_0037: Station_1 NA: Small brush on both</p>
		<b>M</b>	Obstructions (including log jams), vegetation, debris, or sediment are minor and have not impaired channel flow capacity, but should be removed. Sediment shoals have not developed to the extent that they can support vegetation other than non-aquatic grasses. A limited volume of grass and weeds may be present in concrete channel joints and weep holes.	
		<b>U</b>	Obstructions (including log jams), vegetation, debris or sediment have impaired the channel flow capacity. Sediment shoals are well established and support woody and/or brushy vegetation. Sediment and debris removal required to re-establish flow capacity.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Flood Damage Reduction Channels  
Page 1 of 5

# Flood Damage Reduction Channels

For use during Initial and Continuing Eligibility Inspections of flood damage reduction channels

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
				sides of Root Creek: Remove brush (M) BOLI_2015_a_0038: Station_1 NA: Drop structure at STA 24+15: NA (A) BOLI_2015_a_0042: Station_1 NA: Foot bridge near the end of project (STA 18+65). The project extends to STA 16+20 downstream.: NA (A) BOLI_2015_a_0046: Station_1 NA: Access ramp @ STA 21+50: Ensure that the access to the channel is clear and accessible (A)
2. Shoaling <sup>1</sup> (sediment deposition)	<b>M</b>	<b>A</b>	No shoaling or minor, non-vegetated shoaling is present.	BOLI_2015_a_0002: Station_1 NA: Debris basin. Sediment should be removed in this area.: NA (M)
		<b>M</b>	More widespread vegetated and non-vegetated shoaling is present. Non-aquatic grasses are present on shoal. No trees or brush is present on shoal, and channel flow is not significantly reduced. Sediment and debris removal recommended.	BOLI_2015_a_0022: Station_1 NA: Drop structure @ STA 48+50: Remove sediment from concrete areas around drop structure (A)
		<b>U</b>	Shoaling is well established, stabilized by saplings, brush, or other vegetation. Shoals are diverting flow to channel walls. Channel flow capacity is reduced and maintenance is required.	BOLI_2015_a_0030: Station_1 NA: Vegetated shoaling downstream of drop structure at STA 40+25.: NA (M) BOLI_2015_a_0039: Station_1 NA: Shoaling significantly reduces the channel capacity downstream of the drop structure.: Remove sediment in channel (U)
3. Encroachments	<b>A</b>	<b>A</b>	No trash, debris, unauthorized structures, excavations, or other obstructions present within the easement area. Encroachments have been previously reviewed by the Corps, and it was determined that they do not diminish proper functioning of the channel.	BOLI_2015_a_0005: Station_1 NA: Newer pedestrian bridge - appears to be located in unimproved channel area (STA 62+30 - 59+00): NA (A)
		<b>M</b>	Trash, debris, unauthorized structures, excavations, or other obstructions present, or inappropriate activities noted that should be corrected but will not inhibit operations and maintenance or emergency operations. Encroachments have not been reviewed by the Corps.	BOLI_2015_a_0006: Station_1 NA: New Light pole in easement area, installed with concrete footing.: NA (A) BOLI_2015_a_0007: Station_1 NA: Railing in easement.: NA (A)
		<b>U</b>	Unauthorized encroachments or inappropriate activities noted are likely to inhibit operations and maintenance, emergency operations, or negatively impact the integrity of the channel.	BOLI_2015_a_0009: Station_1 NA: 12" CMP pipe from school parking lot through 9" gabions.: NA (A) BOLI_2015_a_0011: Station_1 NA: Well/cistern for the creek. Appears to be noted as "metal shed" near STA 56+00; outside of permanent easement.: NA (A) BOLI_2015_a_0017: Station_1 NA: PVC pipe from school field or pavement. Outside of permanent easement.: NA (A) BOLI_2015_a_0018: Station_1 NA: Large HDPE pipe from field or pavement. Outside of permanent easement.: NA (A) BOLI_2015_a_0023: Station_1 NA: Emergency generator near STA 48+00 +/-: NA (A) BOLI_2015_a_0027: Station_1 NA: 12" CMP pipe (STA 41+00 +/-): NA (A) BOLI_2015_a_0031: Station_1 NA: Residential debris piles: Recommend removing debris piles (M)

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Flood Damage Reduction Channels  
Page 2 of 5

# Flood Damage Reduction Channels

For use during Initial and Continuing Eligibility Inspections of flood damage reduction channels

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
4. Erosion	<b>A</b>	<b>A</b>	No head cutting or horizontal deviation observed.	BOLI_2015_a_0001: Station_1 NA: Access ramp to widened channel area at STA 62+58 +/-: NA (A)
		<b>M</b>	Head cutting and horizontal deviation evident, but is less than 1 foot from the designed grade or cross section.	
		<b>U</b>	Head cutting and horizontal deviation of more than 1 foot from the designed grade or cross section. Corrective actions required to stop or slow erosion.	
5. Concrete Surfaces	<b>A</b>	<b>A</b>	Negligible spalling, scaling or cracking. If the concrete surface is weathered or holds moisture, it is still satisfactory but should be seal coated to prevent freeze/ thaw damage.	BOLI_2015_a_0024: Station_1 NA: Drop structure sta 45+25: NA (A)
		<b>M</b>	Spalling, scaling, and open cracking present, but the immediate integrity or performance of the structure is not threatened. Reinforcing steel may be exposed. Repairs/ sealing is necessary to prevent additional damage during periods of thawing and freezing.	BOLI_2015_a_0033: Station_1 NA: Drop structure (STA 33+60): NA (A)
		<b>U</b>	Surface deterioration or deep cracks present that may result in an unreliable structure. Any surface deterioration that exposes the sheet piling or lies adjacent to monolith joints may indicate underlying reinforcement corrosion and is unacceptable.	BOLI_2015_a_0040: Station_1 NA: Concrete wall located @ STA 24+15 to 23+75 +/-: NA (A)
		<b>N/A</b>	There are no concrete items in the channel.	BOLI_2015_a_0045: Station_1 NA: Station_2 NA: Modification to original debris basin completed by the Bolivar-Richburg Central School District in 2001/2002.: NA (A)
6. Tilting, Sliding or Settlement of Concrete Structures <sup>2</sup>	<b>A</b>	<b>A</b>	There are no significant areas of tilting, sliding, or settlement that would endanger the integrity of the structure.	
		<b>M</b>	There are areas of tilting, sliding, or settlement (either active or inactive) that need to be repaired. The maximum offset, either laterally or vertically, does not exceed 2 inches unless the movement can be shown to be no longer actively occurring. The integrity of the structure is not in danger.	
		<b>U</b>	There are areas of tilting, sliding, or settlement (either active or inactive) that threaten the structure's integrity and performance. Any movement that has resulted in failure of the waterstop (possibly identified by daylight visible through the joint) is unacceptable. Differential movement of greater than 2 inches between any two adjacent monoliths, either laterally or vertically, is unacceptable unless it can be shown that the movement is no longer active. Also, if the floodwall is of I-wall construction, then any visible or measurable tilting of the wall toward the protected side that has created an open horizontal crack on the riverside base of a monolith is unacceptable.	
		<b>N/A</b>	There are no concrete items in the channel.	
7. Foundation of	<b>A</b>	<b>A</b>	No active erosion, scouring, or bank caving that might endanger the structure's stability.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Flood Damage Reduction Channels  
Page 3 of 5

# Flood Damage Reduction Channels

For use during Initial and Continuing Eligibility Inspections of flood damage reduction channels

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
Concrete Structures <sup>3</sup>		<b>M</b>	There are areas where the ground is eroding towards the base of the structure. Efforts need to be taken to slow and repair this erosion, but it is not judged to be close enough to the structure or to be progressing rapidly enough to affect structural stability before the next inspection. For the purposes of inspection, the erosion or scour is not closer to the riverside face of the wall than twice the floodwall's underground base width if the wall is of L-wall or T-wall construction; or if the wall is of sheetpile or I-wall construction, the erosion is not closer than twice the wall's visible height. Additionally, rate of erosion is such that the wall is expected to remain stable until the next inspection.	
		<b>U</b>	Erosion or bank caving observed that is closer to the wall than the limits described above, or is outside these limits but may lead to structural instabilities before the next inspection. Additionally, if the floodwall is of I-wall or sheetpile construction, the foundation is unacceptable if any turf, soil or pavement material got washed away from the landside of the I-wall as the result of a previous overtopping event.	
		<b>N/A</b>	There are no concrete items in the channel.	
8. Slab and Monolith Joints	<b>A</b>	<b>A</b>	The joint material is in good condition. The exterior joint sealant is intact and cracking/desiccation is minimal. Joint filler material and/or waterstop is not visible at any point.	
		<b>M</b>	The joint material has appreciable deterioration to the point where joint filler material and/or waterstop is visible in some locations. This needs to be repaired or replaced to prevent spalling and cracking during freeze/ thaw cycles, and to ensure water tightness of the joint.	
		<b>U</b>	The joint material is severely deteriorated or the concrete adjacent to the monolith joints has spalled and cracked, damaging the waterstop; in either case damage has occurred to the point where it is apparent that the joint is no longer watertight and will not provide the intended level of protection during a flood.	
		<b>N/A</b>	There are no concrete items in the channel.	
9. Flap Gates/ Flap Valves/ Pinch Valves <sup>4</sup>	<b>U</b>	<b>A</b>	Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required.	BOLI_2015_a_0026: Station_1 NA: 12" CMP drain pipe with flap gate (STA 41+50 +/-). The flap is separated from the concrete and no longer will function properly.: Repair flap gate (U)
		<b>M</b>	Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance.	
		<b>U</b>	Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced.	
		<b>N/A</b>	There are no flap gates.	
10. Riprap Revetments & Banks	<b>M</b>	<b>A</b>	No riprap displacement or stone degradation that could pose an immediate threat to the integrity of channel bank. Riprap intact with no woody vegetation present.	BOLI_2015_a_0008: Station_1 NA: Gabions (STA 59+00 - 56+00): Remove vegetation from gabions. (A) BOLI_2015_a_0025: Station_1 NA: Gabion dike (STA 40+50 - STA 43+20): Sponsor should remove the vegetation from the gabion dike area (M)
		<b>M</b>	Minor riprap displacement or stone degradation that could pose an immediate threat to the integrity of the channel bank. Unwanted vegetation must be cleared or sprayed with an appropriate herbicide.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Flood Damage Reduction Channels  
Page 4 of 5

# Flood Damage Reduction Channels

For use during Initial and Continuing Eligibility Inspections of flood damage reduction channels

Rated Item	Rating	Rating Guidelines		Location/Remarks/Recommendations
		<b>U</b>	Significant riprap displacement, exposure of bedding, or stone degradation observed. Scour activity is undercutting banks, eroding embankments, or impairing channel flows by causing turbulence or shoaling. Rock protection is hidden by dense brush, trees, or grasses.	BOLI_2015_a_0043: Station_1 NA: Station_2 NA: Modification to original debris basin completed by the Bolivar-Richburg Central School District in 2001/2002.: NA (A)
		<b>N/A</b>	There is no riprap protecting this feature of the segment / system, or riprap is discussed in another section.	
11. Revetments other than Riprap	<b>A</b>	<b>A</b>	Existing revetment protection is properly maintained, undamaged, and clearly visible.	BOLI_2015_a_0015: Station_1 NA: Sheet pile wall w/fencing (STA 52+00 - 49+30); appears to be outside of permanent easement.: NA (A) BOLI_2015_a_0019: Station_1 NA: Fence loose at the bottom. Outside of permanent easement.: NA (A)
		<b>M</b>	Minor revetment displacement or deterioration that does not pose an immediate threat to the integrity of the levee. Unwanted vegetation must be cleared or sprayed with an appropriate herbicide.	
		<b>U</b>	Significant revetment displacement, deterioration, or exposure of bedding observed. Scour activity is undercutting banks, eroding embankments, or impairing channel flows by causing turbulence or shoaling. Revetment protection is hidden by dense brush and trees.	
		<b>N/A</b>	There are no such revetments protecting this feature of the segment / system.	

<sup>1</sup> If weather and flow conditions allow, inspectors should walk in the channel and probe shoal areas in order to estimate extent of blockage of the cross-sectional area where shoaling is present.

<sup>2</sup> The sponsor should be monitoring any observed movement to verify whether the movement is active or inactive.

<sup>3</sup> Inspectors must have as-built drawings available during the inspection so that the lateral distance to the heel and toe of the floodwalls can be determined in the field.

<sup>4</sup> Proper operation of this item must be demonstrated during the inspection.

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Flood Damage Reduction Channels  
Page 5 of 5



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0041 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0041_1.jpg <b>Rated Item:</b> 1. Unwanted Vegetation Growth <b>Caption:</b> Rating: Unacceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0041 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0041_2.jpg <b>Rated Item:</b> 1. Unwanted Vegetation Growth <b>Caption:</b> Rating: Unacceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 1 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

 <p>10/21/2015 3:25 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0041 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0041_3.jpg <b>Rated Item:</b> 1. Unwanted Vegetation Growth <b>Caption:</b> Rating: Unacceptable</p>
 <p>10/21/2015 3:26 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0041 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0041_4.jpg <b>Rated Item:</b> 1. Unwanted Vegetation Growth <b>Caption:</b> Rating: Unacceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 2 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

 A photograph showing a dense thicket of bare, brown brush and trees along a grassy area. A concrete structure is visible on the left side of the frame. A red timestamp '10/21/2015 2:07:09 PM' is visible in the bottom right corner of the photo.	<p><b>Inspect ID:</b> BOLI_2015_a_0004 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0004_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>
 A photograph showing a dense thicket of bare, brown brush and trees along a grassy area. A concrete structure is visible on the right side of the frame. A red timestamp '10/21/2015 2:07:09 PM' is visible in the bottom right corner of the photo.	<p><b>Inspect ID:</b> BOLI_2015_a_0004 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0004_2.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 3 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0010 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0010_2.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Minimally Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0010 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0010_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Minimally Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 4 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0012 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0012_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0013 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0013_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 5 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0014 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0014_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0016 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0016_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 6 of 25



## Photos



For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0020 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0020_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Minimally Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0021 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0021_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Minimally Acceptable</p>



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0029 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0029_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0032 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0032_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Minimally Acceptable</p>



US Army Corps  
of Engineers®


Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 8 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0034 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0034_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Minimally Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0035 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0035_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 9 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

 <p>10/21/2015 3:16:48 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0036 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0036_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>
 <p>10/21/2015 3:18:52 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0037 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0037_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Minimally Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 10 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0038 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0038_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0042 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0042_1.jpg <b>Rated Item:</b> 1. Vegetation and Obstructions <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 11 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0002 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0002_4.jpg <b>Rated Item:</b> 2. Shoaling (sediment deposition) <b>Caption:</b> Rating: Minimally Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0022 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0022_1.jpg <b>Rated Item:</b> 2. Shoaling (sediment deposition) <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 12 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

 <p>10/21/2015 2:39:45 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0022 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0022_2.jpg <b>Rated Item:</b> 2. Shoaling (sediment deposition) <b>Caption:</b> Rating: Acceptable</p>
 <p>10/21/2015 2:39:50 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0022 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0022_3.jpg <b>Rated Item:</b> 2. Shoaling (sediment deposition) <b>Caption:</b> Rating: Acceptable</p>





US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 13 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0030 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0030_1.jpg <b>Rated Item:</b> 2. Shoaling (sediment deposition) <b>Caption:</b> Rating: Minimally Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0039 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0039_1.jpg <b>Rated Item:</b> 2. Shoaling (sediment deposition) <b>Caption:</b> Rating: Unacceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 14 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0005 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0005_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0006 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0006_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 15 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0007 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0007_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0009 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0009_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 16 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

 <p>10/21/2015 2:16:17 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0011 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0011_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>
 <p>10/21/2015 2:17:01 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0011 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0011_2.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 17 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0017 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0017_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0018 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0018_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 18 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0023 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0023_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0027 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0027_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 19 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

 <p>10/21/2015 2:27:51 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0031 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0031_1.jpg <b>Rated Item:</b> 3. Encroachments <b>Caption:</b> Rating: Minimally Acceptable</p>
 <p>10/21/2015 2:01:32 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0001 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0001_1.jpg <b>Rated Item:</b> 4. Erosion <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 20 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0024 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0024_1.jpg <b>Rated Item:</b> 5. Concrete Surfaces <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0033 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0033_1.jpg <b>Rated Item:</b> 5. Concrete Surfaces <b>Caption:</b> Rating: Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 21 of 25

## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<p><b>Inspect ID:</b> BOLI_2015_a_0040 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0040_1.jpg <b>Rated Item:</b> 5. Concrete Surfaces <b>Caption:</b> Rating: Acceptable</p>
	<p><b>Inspect ID:</b> BOLI_2015_a_0026 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0026_1.jpg <b>Rated Item:</b> 9. Flap Gates/ Flap Valves/ Pinch Valves <b>Caption:</b> Rating: Unacceptable</p>



US Army Corps  
of Engineers®



Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 22 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

	<b>Inspect ID:</b> BOLI_2015_a_0026 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0026_2.jpg <b>Rated Item:</b> 9. Flap Gates/ Flap Valves/ Pinch Valves <b>Caption:</b> Rating: Unacceptable
	<b>Inspect ID:</b> BOLI_2015_a_0026 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0026_3.jpg <b>Rated Item:</b> 9. Flap Gates/ Flap Valves/ Pinch Valves <b>Caption:</b> Rating: Unacceptable



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems

 <p>10/21/2015 2:43:02 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0008 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0008_1.jpg <b>Rated Item:</b> 10. Riprap Revetments &amp; Banks <b>Caption:</b> Rating: Acceptable</p>
 <p>10/21/2015 2:43:43 PM</p>	<p><b>Inspect ID:</b> BOLI_2015_a_0025 <b>Title:</b> USACE_CELRP_BOLI_2015_a_0025_1.jpg <b>Rated Item:</b> 10. Riprap Revetments &amp; Banks <b>Caption:</b> Rating: Minimally Acceptable</p>



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 24 of 25



## Photos

For use during Initial and Continuing Eligibility Inspections of levee segments / systems



**Inspect ID:** BOLI\_2015\_a\_0015 **Title:** USACE\_CELRP\_BOLI\_2015\_a\_0015\_1.jpg  
**Rated Item:** 11. Revetments other than Riprap **Caption:** Rating: Acceptable



**Inspect ID:** BOLI\_2015\_a\_0019 **Title:** USACE\_CELRP\_BOLI\_2015\_a\_0019\_1.jpg  
**Rated Item:** 11. Revetments other than Riprap **Caption:** Rating: Acceptable



US Army Corps  
of Engineers®

Flood Damage Reduction Segment / System  
Inspection Report  
Bolivar, NY (BOLI)

Photos  
Page 25 of 25